Date Issued November 1970





TECHNICAL NOTE

U.S. DEPARTMENT OF THE INTERIOR - BUREAU OF LAND MANAGEMENT

PERMA MARK SURVEYOR'S MARKER

they fix it!"



Short lengths of reinforcing rod or pipe are often driven into the ground to form semi-permanent survey markers or reference points. They generally are left projecting a few inches above the ground surface.

To correct a potential hazard to people and livestock, especially horses, it has been suggested a yellow plastic cap be installed on the marker. The color also calls attention to the marker, making it easier to find or avoid, as the case may be.

These inexpensive caps are available from Forestry Suppliers, Inc., 205 W. Rankin Street, Box 8397, Jackson, Mississippi, 39204

| Stock | Size | Fits | Price per 100 |
|-------|-----------|------------------------|---------------|
| 39494 | 1/2" plug | 1/2" pipe or #3 re-bar | \$10.00 |
| 39495 | 3/4" plug | 3/4" pipe or #4 re-bar | 11.00 |
| 39496 | 1" plug | 1" pipe or #5 re-bar | 12.50 |

. . A March 2 . 1914

BIOM BADIMHOST

PARTIES AND THE PRESENCE OF THE PROPERTY OF TH

many recognitive area with

The state of the s

or become the most wrist and laure to the control of the most of the control of t

The terror of this paper of the last of the first and the second of the

printed an article and the art of the first for the article Significance, and the article and the article and the article article and the article article article and the article arti

202 Aug 2027 Aug 2027 Aug

and a first when the same and a second resident and a second resident and a second as a first of the second resident and a second resident as the second resident resident as the second resident resident as the second resident res